

H23061 JG



A  62PCS	H 250MM  2PCS	O 3.5*35  8PCS
B 62PCS	I  2PCS	P 14PCS
C 8*40  14PCS	J 96MM  3PCS	Q Φ60 3PCS
D 7*50 10PCS	K 4*18 6PCS	R  1PCS
E 250MM  2PCS	L 3*12  14PCS	S  2PCS
F 250MM  2PCS	M 3.5*14  28PCS	
G 250MM  2PCS	N 3.5*16  4PCS	

1  250*180 1 PCS	2  250*180 1 PCS	3  990*180 1 PCS	4  990*180 1 PCS	5  250*160 2 PCS
6  1100*335 1 PCS	7  250*318 1 PCS	8  772*318 1 PCS	9  772*318 1 PCS	10  772*318 1 PCS
11  162*282 1 PCS	12  250*80 1 PCS	13  250*60 1 PCS	14  250*80 1 PCS	15  280*162 1 PCS

16



803*162 1 PCS

17



819*990 1 PCS

18



968*260 1 PCS

19



627*260 1 PCS

20



550*278 1 PCS

21



278*160 1 PCS

22



536*160 1 PCS

23



250*100 2 PCS

24



250*100 2 PCS

25



195*100 1 PCS

26



485*100 1 PCS

27



234*60 1 PCS

28



205*244 1 PCS

29



495*244 1 PCS

Hardware installation demonstration

NOTE:Please make sure "A"hardware tightened and can't be pulled out!

I



II



III



IV

Scan QR code for assembly video



	A*34	put A on board ③④⑥⑮
	C*6	put C on board ⑦⑬⑯



	A*18
	C*4
	E*2
	F*2
	M*8

put A on board ⑧⑨⑩

put C on board ⑧⑨⑩⑪

③



	C*4
	D*3

put C on board ⑰

④







Make sure the arrow on the screw align to the hole on the side.

	B*8	put B on board ①②⑤

5





Make sure the arrow on the screw
align to the hole on the side.

	B*8
	D*7

put B on board ①②⑤

⑥







Make sure the arrow on the screw
align to the hole on the side.

	B*7	put B on board ⑦⑫⑬⑭

⑦

Make sure the arrow on the screw align to the hole on the side.





	B*9	put B on board ⑦⑪⑫⑬⑭

⑧





Make sure the arrow on the screw align to the hole on the side.

	B*6	put B on board ⑨⑪⑯

⑨



Make sure the arrow on the screw align to the hole on the side.

	B*2	put B on board ⑯

⑩



Make sure the arrow on the screw align to the hole on the side.



	B*12	put B on board ⑧⑨⑩⑪⑮⑯

⑪



	L*14
	P*14

⑫



	A*10
	I*2
	J*3
	K*6
	M*4
	N*4
	R*1

put A on board ㉑㉒㉖

⑬

Make sure the arrow on the screw align to the hole on the side.











	B*1
	0*8

put B on board ㉗

14



Make sure the arrow on the screw align to the hole on the side.

	B*9
	G*2
	H*2
	M*8

put B on board ㉓㉔㉗

⑮



	M*8

⑯



	Q*3

⑰



	S*2

⑱



⑲



---END---