
Assembly Instructions///




Parts List				
lable	Pictu	re	Description	on Qty
A				1
В				4
Hardware List				
lable	Picture	Description	Size	Qty
H-1		Bolt	M6x15 mm	12
Tool List				
lable	Picture	Description		Qty
T-1		Allen Key		1



ATTENTION:

DO NOT COMPLETELY TIGHTEN ANY SCREWS UNTIL ALL PARTS ARE IN PLACE

Step 1



Step 2

