
















Assembly Instructions

W1673106108
W1673106109
W1673106110
W1673106111







| | | | | |
|---|--|---|--|---|
| <p>A</p>  <p>M4X8 x30</p> | <p>B</p>  <p>x10</p> | <p>C</p>  <p>x4</p> | <p>D</p>  <p>M4X20 x4</p> | <p>E</p>  <p>x4</p> |
| <p>F</p>  <p>x4</p> | <p>G</p>  <p>x4</p> | <p>H</p>  <p>x2</p> | <p>I</p>  <p>M5X50 x2</p> | |




4






5






6




7



8



9



10

