



















# ASSEMBLY INSTRUCTIONS













SKU:W37023955




## Part List

				
① x1Pc	② x1Pc	③ x1Pc	④ x1Pc	⑤ x1Pc
				
⑥ x1Pc	⑦ x1Pc	⑧ x1Pc	⑨ x1Pc	⑩ x1Pc
				
⑪ x1Pc	⑫ x4Pcs	⑬ x4Pcs	⑭ x4Pcs	⑮ x4Pcs
				
⑯ x4Pcs				





## Hardware List


				
Ax44Pcs	Bx44Pcs	M4x14 Cx76Pcs	M4x35 Dx16Pcs	Ex4Pcs
				
Fx5Pcs	M5x18 Gx10Pcs	Hx4Pcs	Kx2Pcs	Lx1Pc
				
Mx1Pc	Nx4Pcs			






PLEASE BE CAREFUL. DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !



# Step 1

			
Mx1Pc	Cx32Pcs	Nx4Pcs	Ex4Pcs




# Step 2


		
Mx1Pc	Cx16Pcs	Hx4Pcs



### Step 3



### Step 4






# Step 5



Mx1Pc



Bx8Pcs





# Step 6






Mx1Pc




Bx4Pcs









# Step 7

		
Mx1Pc	Bx8Pcs	Lx1Pc



# Step 8

				
Mx1Pc	Kx2Pcs	M5x18 Gx2Pcs	Fx1Pc	M4x14 Cx4Pcs



# Step 8




Mx1Pc



M4x14

Cx8Pcs



# Step 10



Mx1Pc




Ax16Pcs





M4x14

Cx16Pcs









Hx4Pcs



× 4

# Step 11

				
Mx1Pc	Bx16Pcs	Dx16Pcs	Gx8Pcs	Fx4Pcs



# Step 12

