




① x1




② x1




③ x1




④ x1



⑤ x1




⑥ x1



⑦ x1




⑧ x4



Ax1



M6x25
Bx12




M6x40
Cx19



Ø10x10
Dx19



M4x20
Ex4




Fx2




M4x10
Gx32




Hx4




1




2




3




4




5




6




7




8




9



10



11



12

