## Tighten all the screws to 70% of ASSEMBLING INSTRUCTION maximum tightness. Η D **PARTS LIST** B X2 AX1 C X2 D X2 E X2 K M8X70mm M8X22mm M8 M8 F X4 GX8 **H X8** 1 X8 JX1 M4X45mm Tighten all the screws to 100% of maximum tightness. K X8