ASSEMBLY INSTRUCTION

Hardware

Α	В	С	D	E	F	G	1	2	3	4	5
9 M6*16	M6*30	M6*65	© ø6*ø16*1.5	5MM	9 M6	10MM					*
X4	X1	X4	Х4	X1	X4	X1	X1	X1	X1	X1	X1

Assemble Step

