
Cat treedmill 4.0 XL installation

Instructions Hint:

Do not tighten the mounting screws to the end at one time, and tighten them again after a single component is installedand formed!



and torque with S-nuts.

* ${f Q}$ Long screw

Detailed installation steps:

