















Assembly Instructions

W1673121039
W1673121040
W1673121041
W1673121042






 60 MIN		
---	---	---






<p>A</p>  <p>M4X8 x24</p>	<p>B</p>  <p>M5X8 x8</p>	<p>C</p>  <p>x4</p>	<p>D</p>  <p>x2</p>	<p>E</p>  <p>M6X45 x8</p>
<p>F</p>  <p>x2</p>	<p>G</p>  <p>x2</p>	<p>H</p>  <p>x2</p>	<p>I</p>  <p>M5X50 x2</p>	




1





2





3





4






5



6






7




8

6

7



9



10

