



















ASSEMBLY INSTRUCTIONS













SKU:W37023955




Part List

				
① x1Pc	② x1Pc	③ x1Pc	④ x1Pc	⑤ x1Pc
				
⑥ x1Pc	⑦ x1Pc	⑧ x1Pc	⑨ x1Pc	⑩ x1Pc
				
⑪ x1Pc	⑫ x4Pcs	⑬ x4Pcs	⑭ x4Pcs	⑮ x4Pcs
				
⑯ x4Pcs				





Hardware List


				
Ax44Pcs	Bx44Pcs	M4x14 Cx76Pcs	M4x35 Dx16Pcs	Ex4Pcs
				
Fx5Pcs	M5x18 Gx10Pcs	Hx4Pcs	Kx2Pcs	Lx1Pc
				
Mx1Pc	Nx4Pcs			






PLEASE BE CAREFUL. DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWER TOOLS !



Step 1

			
Mx1Pc	Cx32Pcs	Nx4Pcs	Ex4Pcs






Step 2

		
Mx1Pc	Cx16Pcs	Hx4Pcs






Step 3

	
Mx1Pc	Ax28Pcs



Step 4

	
Mx1Pc	Bx8Pcs






Step 5



Mx1Pc



Bx8Pcs





Step 6




Mx1Pc



Bx4Pcs



Step 7




Mx1Pc



Bx8Pcs




Lx1Pc



Step 8



Mx1Pc



Kx2Pcs



M5x18

Gx2Pcs




Fx1Pc






M4x14

Cx4Pcs









Step 8

	
Mx1Pc	M4x14 Cx8Pcs








Step 10


			
Mx1Pc	Ax16Pcs	M4x14 Cx16Pcs	Hx4Pcs



× 4

Step 11

				
Mx1Pc	Bx16Pcs	Dx16Pcs	Gx8Pcs	Fx4Pcs



Step 12

