

25202203921



CHAOZHOU MORNING YU TECHNOLOGY

CO., LTD.

**ROOM 01, ROOM 601, STAIRCASE 2, BUILDING
40, HONGTIAN PLAZA, XIANGQIAO DISTRICT,
CHAOZHOU, GUANGDONG, CHINA**

22

M1002

PH

EN 997 — CL 1 – 6A

CERTIFICATE Of Conformity

Certificate No: 25202203921
Applicant: CHAOZHOU MORNING YU TECHNOLOGY CO., LTD.
Address of Applicant: ROOM 01, ROOM 601, STAIRCASE 2, BUILDING 40, HONGTIAN PLAZA,
XIANGQIAO DISTRICT, CHAOZHOU, GUANGDONG, CHINA
Product: WALL HUNG TOILET
Brand: /
Type designation: M1002, M1009, M1010
Technical data: Wall-hung WC pan with integral trap, personal hygiene, Type 1, nominal flush
volume of 6L

The submitted samples of the above product have been tested for CE marking according to the following European Regulation:

(EU)No.305/2011- the Construction Products Regulation

Standard used for showing compliance with the essential requirements in the specified directive:

Standard	Test report	Issued by	Date
EN 997:2018	25202203921	IQTC of FSCIQ	Oct. 14, 2022

The referred test report shows that the product complies with standard recognized as giving presumption of compliance with the essential requirements in the specified EU Directive.

After preparation of the necessary technical documentation as well as the conformity declaration the CE marking as shown below can be affixed on the product. Other relevant Directives have to be observed.

This document is the property of Comprehensive Technology Centre of Foshan Customs, and it is not transferable. Only the applicant may reproduce this certificate.


YUAN FANGLI
Director



Issue Date: Oct. 14, 2022

Expiration Date: Oct. 13, 2025

Note: This certificate is part of the full report and should be read in conjunction with it.



中国认可
国际互认
检测
TESTING
CNAS L1978



TEST REPORT

REPORT NO. : 25202203921

SAMPLES: WALL HUNG TOILET

APPLICANT: CHAOZHOU MORNING YU TECHNOLOGY
CO., LTD.

DATE OF TEST: 12/10/2022~13/10/2022 (DD/MM/YY)




STATE KEY TESTING LABORATORY OF BUILDING CERAMICS AND SANITARY WARE
COMPREHENSIVE TECHNOLOGY CENTRE OF FOSHAN CUSTOMS

TEST REPORT

Report No.: 25202203921

Page 2 of 4

Name of Sample	WALL HUNG TOILET	Type	INDEPENDENT WC PAN, WALL-HUNG, SINGLE FLUSH, TYPE 1, NOMINAL FLUSH VOLUME OF 6L
Mark of Samples	M1002	Description of Samples	The samples are sound, intact and fit for test.
Quantity of Samples	1 Set	Nominal Size	—
Applicant	CHAOZHOU MORNING YU TECHNOLOGY CO., LTD.	Address of Applicant	ROOM 01, ROOM 601, STAIRCASE 2, BUILDING 40, HONGTIAN PLAZA, XIANGQIAO DISTRICT, CHAOZHOU, GUANGDONG
Telephone of Applicant	—	Fax of Applicant	—
Source of Samples	Sample selected by applicant	Received on	10/10/2022
Test Standard	EN 997:2018 <i>WC pans and WC suites with integral trap</i>		
Conclusion of Test	The results conform to the requirements of EN 997: 2018 with respect to the test items.		
Stamp of Test Unit	 <p>Date: 14/10/2022</p>	Address of Test Unit	Address: 2/F, Building 18, Lanshi International Metal Exchange Center, Kuiqiyi Road, Chancheng District, Foshan, Guangdong, China (528000) Tel: 86-757-83960558 86-757-83827991 E-mail: fsiqtc@163.com
Notes	<ol style="list-style-type: none"> All inspections are carried out conscientiously to the best of our knowledge and ability. This report does not in any respect absolve the other related parties from his contractual and legal obligations. This report shall not be reproduced, except in full, without the prior written approval from the issuing laboratory. The results in this report apply to the samples only. The sample information are declared by applicant, and laboratory is not responsible for the authenticity. 		
Possible test case verdicts	<ol style="list-style-type: none"> P(ass) : test item does meet the requirement. N/A : test case does not apply to the test item. F(ail) : test item does not meet the requirement. —: verdict/test was not carried out. 		

Tested by 杨明 Inspected by 李 Approved by 李

TEST REPORT

Report No.: 25202203921

Page 3 of 4

Remark of applicant

The test report data was based on item No.M1002, in a family of wall hung toilet. All items in the family are same in material, method of manufacture and finish surface characteristics, except for the design of appearance.

Items in the family:

M1002, M1009, M1010

Photo of Samples



M1002

TEST REPORT

Report No.: 25202203921

Page 4 of 4

EN 997:2018 <i>WC pans and WC suites with integral trap</i>				
Clause	Properties	Requirements	Results	Verdicts
5.1	Depth of water seal	≥50 mm	66mm	Pass
5.2	Flushing requirements			
	Wash of bowl	The arithmetic average of any unflushed area below the rim and above the surface of the water in the trap shall not be more than 50 cm ² after five flushing operations.	No sawdust remaining	Pass
	Flushing of toilet paper	12 sheets of toilet paper shall be flushed out of the WC pan a minimum of 4 times out of five tests.	Compliant	Pass
	Flushing of fifty small plastic balls	Each with 50 balls, a minimum of 85% of the balls shall be flushed out of the WC pan.	—	N/A
	Oversplashing	Flushing water shall not splash beyond the rim of the bowl and wet the floor. Only a few small drops are permissible.	Compliant	pass
	After-flush volume	An after-flush volume of 2.5L or 2.8L as appropriate is required.	3.0L~3.2L	Pass
5.3	Water absorption	Average: $E \leq 0.5\%$	Average: 0.12%	Pass
5.4	Static load	Wall-hung and non-ceramic WC pans and suites shall withstand a force of (4.00 ± 0.05) kN without showing any evidence of cracking or permanent deformation.	No cracking or permanent deformation	Pass
5.8	Sub-types of independent WC pans, close-coupled suites and one-piece WC pans			
5.8.1	Nominal flush volume	5.9L~6.0L	6.0L	Pass

*** **

End of Test Report